Beyond Standard: Do the Marine Engine Officers Competence?

Antoni Arif Priadi¹, Imam Fahcruddin², Nafi Almuzani² and Akhmad Kasan Gupron²

¹Nautical Department, Sekolah Tinggi Ilmu Pelayaran (STIP) Jakarta, Indonesia ²Engine Department, Sekolah Tinggi Ilmu Pelayaran (STIP) Jakarta, Indonesia

Keywords: Competency, Marine engine officer, importance performance analysis, gap analysis

Abstract:

Indonesia has an important role in the world maritime industry through the large number of Indonesian registered ships as well as the number of marine engine officers. The marine engine officers had supplied the national ship flag as well as the foreign ship flag. Therefore, there is a need to evaluate the future competency of marine engine officers to serve the industry as the aim of this research. The gap analysis method is applied to compare the expectation and the perception of the competency variables as well as Important Performance Analysis (*IPA*). The result showed that the level conformity between expectation and perception for the marine engineering variable is 78.92% followed by 77.69% of electrical electronics and control engineering variable, 77.97% of maintenance and repair variable, 77.34% of controlling the operation of the ship and care for persons on board variable and 80.92% of soft skill variable. The gap between perceptions and expectations of the marine engine competency is negative. Yet, based on the Important Performance Analysis (*IPA*) showed that there are 8 variables need to be improved and 8 variables need to be maintained. Furthermore, there are 4 variables which are low priority. Whereas, there are 8 variables which are over acts. Future research by using industry perspective needs to be done to correct the future level of marine engine officer competency.

1 INTRODUCTION

Indonesia is an archipelagic state which consists of 70% of sea area. The sea area of Indonesia covers 5.8 million km square with length of coast line is 95,181 km. Based on this fact, the sea transportation has important role to connect the 17.504 islands. One of the sea transportation mode is ship which the number of Indonesian registered ships are more than 17.000 ships. As the ship needs to be operated by crew, one of the crew profession is the marine engineer officer.

The number of Indonesian seafarers are 875.933 in 2017. These number includes the number of seafarers who work for foreign ships. For the marine engine officers, the number is around 47.000. Their certificates are according to the requirements of Standards of Training, Certification and Watchkeeping for Seafarers (STCW) 1978 Amendments 2010.

The marine engine officers, many of whom work in national companies and few of them work for international companies. Whereas in accordance with the data from BIMCO in 2015 there is still a shortage of thousands of ship officers including marine engine officers. This should be used by Indonesian marine engine officers to compete filling the international market. Of course to fill the international market Indonesian marine engineer officers need to have competencies of international standards and even must be above international standards. Therefore, analysis an competencies of the Indonesian marine engine officers is required. It is expected to provide an overview of the advantages possessed by the marine Indonesian engine officers in addition to the description of areas that need to get attention for future improvement.

There are a lot number of Indonesian seafarers who did not passed to work for international company due to the level of communication, the level of discipline and the some part of homesick culture. These could be used as the indicators of usage Indonesian seafarers in the international market. (Syamsudin, 2007)

Education and training are really required to improve the human resources quality in shipping service. The role of education and training institute is very important to produce national seafarers who have high quality to compete in international market.

Recently, Indonesia has sufficient number of seafarers, yet the industry requires the competent seafarer according to the certificate possesed.

Human competency can be known by people who see and assess the activities that he did. A competency appraiser may come from a person who has more knowledge in the field or a superior of the human services user who has the competency. Perception is the work of the brain in understanding and assessing something that happens around it (Waidi, 2006). Furthermore, perception is a process that starts from the utilization of the human senses, from sight, hearing and others to the formation of responses that occur within the individual so that the individual is aware of everything in the environment through the senses he has. The assessment of competency can be done by comparing the characteristics underlying the effectiveness of individual performance (competence) with the required job competence (Moeherino, 2012). By using perception, we are able to know whether a person has the competencies required in that position.

The expectations reflect individual perceptions of the ability to clearly define goals, to take the initiative and to retain the motivation to use strategies, and to develop specific strategies to achieve those goals (Snyder, 1994). The expextation is something that can be formed and can be used as a step for change. Profitable changes can cause the individual to achieve a better life. Each individual has the ability to form expectations because they have a basic component in the cognitive abilities needed to produce thoughts of hope. Changes related to those expectations require the formation and maintenance of personal power in the context of a supportive or supportive relationship. By comparing perception and expectation, we can know whether there is a gap in achieving a goal.

From the problems presented above, researchers are interested to examine the perceptions and expectations of seafarers' competence, especially Indonesian marine engine officers. This is very important for policy makers to know which indicators are gaps so that solutions and improvement can be applied. This research is also important for the shipping companies to understand what is the strong factor of Indonesian marine engine officers as well as the area which needs to be developed during on board ship.

2 RESEARCH METHOD

To start with the method, this research is a quantitative descriptive study using the user

approach. The research sample, consisting of 100 respondents, was selected by means of the accidental sampling technique. The respondents were the marine engine officers who were identified proper to fill the questionairre. The data were collected through questionnaires. The analysis used is the Gap Analysis (Franklin, 2005) and *IPA* (John, 1977).

The questionnaire survey consists of the several group questions. First is the questions of general information of the respondent. Then, the questions asked respondents to level the degree of perception and expectation of each variable. To extract the level of perception, the respondents were asked to rate each variable on the five–point using Likert scale, varying from "strongly unnecessary" (1) to "strongly necessary" (5). Whereas for the level of expectation, the five – point using Likert scale is used, varying form "strongly unexpected" (1) to "strongly expected" (5).

A questionnaire survey was designed into five competency categories. The first competency category is related to the marine engineering which consists of 7 variables. The second competency categoy of questionnaire survey consists of 2 variables which related to the electrical, electronic and control engineering. The third competency of the questionnaire survey category consists of 3 variables which related to the maintenance and repair. The fourth competency of questionnaire survey category consists of 8 variables which related to controlling the operation of the ship and care for persons on board. The last competency of the questionnaire survey category is related to the soft skill which consist of 11 variables. The detail of variables is arranged as diplayed in the Table 1.

Table 1: The variables under first until five competency.

Var.	Description of Variable	Competency
V1	Shipboard engine operation	
V2	Maintain a safe Engine	1
	Room watch	
V3	Understand the	
	characteristics the main	
	engine of diesel, steam	
	turbine and gas, including	
	the- speed, output and fuel-	
V4	oil consumption.	Marine
V4	Practical knowledge on	engineerin
	operation, supervision,	g
	performance assessment and security maintenance of the	
	installation of the main	
	engine and auxiliary	
	machineries.	
V5	Respond to emergencies	1
V6	Manage fuel oil, lubrication]
	and ballast operation.	
V7	Maneuver the ship	
V8	Operate electrical, electronic	Electrical,
	and control systems	electronic
V9	Maintenance and repair of	and control
	electrical and electronic	engineerin
	equipment	g
V10	Manage safe and effective	
	maintenance and repair	
	prosedures	
V11	Detect and identify the	Maintenance
50	causes of engine damage	and repair
V12	and repair it. Ensure safe working	
V 12	practices sale working	
V13	Ensure compliance with	
	pollution prevention	
	requirements	
V14	Maintain the seaworthiness	
	of the ship	
V15	Prevent, control and fight	Controllin
	fires on board	g the
V16	Operate life-saving	operation
7717	appliances	of the ship
V17	Apply medical first aid on	and care
V18	board ship	for persons on board
V 18	Monitor compliance with legislative requirements	on ooard
V19	Application of leadership	}
V 17	and team working skills	
V20	Contribute to safety of	1
1 20	personnel and ship	
V21	Team work	
V22	Organize and coordinate	0.0.1.11
. 22	staff to achieve company	Soft skill
	objectives	

Var.	Description of Variable	Competency
V23	Continuosly learning and wilingness to receive feed	
	back from super ordinate	
V24	Finding problem	
V25	Using and acting upon information	
V26	Integrity	
V27	Motivation	
V28	Persistence and courage in facing problem	
V29	Leadership pattern	
V30	Wise attitude	
V31	Responbility	

The survey was conducted at Sekolah Tinggi Ilmu Pelayaran (STIP) Jakarta during September to October 2017. Several manners were used to motivate the questionnaires to the respondents. Nevertheless, to encourage the respondents in participating the survey, face to face and using google form was preferred. Doing so, the response rate increased. Gap analysis is used to determine the steps which are need to be choosen for further improvement from recent condition to the expected condition in the future. The gap analysis is also a means of comparison between actual performance and future performance. This gap analysis also identifies the action plan to achieve the future performance. Furthermore, the gap analysis method is used for analysis between the perception and expectation of Indonesian marine engine officer competencies. The gap calculation is acquired from the mean score of expectation after being deducted with mean score of perception. At the end, the gap analysis method is fulfilled for five competency of variables groups.

3 RESULTS AND DISCUSSION

First of all, the respondent profiles include the respondent's age, education background, competency certificate degree and sea service. For the respondent age, there are 37% have age less than 31 years old, followed by 51% of respondent have middle age between 31-50 years old and small percentage for respondent's age more than 51 years old. Further, regarding to the educational background, there are 7% respondents graduated from senior high school, 33% graduated from diploma, 47% graduated from bachelor, and 7% graduated from master. Then 7% of respondents is categorized with other education background. Based on the competency certificate degree, 40% of respondents were marine engine officers class III, 28% of respondents were marine engine officers class II, and 26% of respondents were marine engine officers class I. In addition, 7% of respondents were categorized with other employment background. It could be concluded that all respondents had experience as the marine engine officer on board vessel.

In addition, they have experience as the chief engineer and they have sub ordinate. Their experiences are very helpful for them during filling the questionnaire as they have seen and observed the ability of their marine engineer. As the result, the questionaire result is more accurate. For the sea service experiences, the 47% respondent has 1 to 3 years experiences. Meanwhile, those who have 4 to 6 years experiences are only 14% respondents accounted and 40% have experienced more than 6 years.

The assessment of marine engine officer competency is determined by calculating the level of perception and expectation on each competency group. The result of group 1, marine engineering competencies, is presented in Table 2.

Table 2: The competency conformity level of group 1

Var.	Mean of Perceptions	Mean of Expectations	Conformity Level	Gap (E – P)
V1	3.42	4.12	83.01 %	0.58
V2	3.34	4.17	80.10 %	0.66
V3	3.08	4.16	74.04 %	-0.08
V4	3.29	3.90	84.36 %	0.71
V5	3.30	4.26	77.46 %	0.20
V6	3.36	4.23	79.43 %	0.64
V7	3.16	4.24	74.53 %	-0.16

From Table 2, it can be shown that the suitability level of marine engineering competencies for all variables did not achieve 100%. Thus, the expectation of user is higher than the marine engine officer competencies currently. Therefore, there is a need to improve this area for future.

Further, the same procedure is applied for the group 2 competency which is electrical, electronic and control engineering as presented in Table 3.

Table 3: The competency conformity level of group 2

Var.	Mean of Perceptions	Mean of Expectations	Conformity Level	Gap (E – P)
V8	3.04	4.20	72.38 %	1.16
V9	3.33	4.00	83.25 %	0.67

From Table 3, it can be shown that the suitability level of electrical, electronic and control engineering competencies for two variables did not reach 100%. It means that the expectation of user is higher than the marine engine officer competencies currently. Therefore, it is necessary to improve this area for future.

The next suitablity level measurement is applied for the group 3 competency which is maintenance and repair competency. The result is presented in table 4. It can be shown that the suitability level of maintenance and repair competencies for three variables did not reach 100%.

Table 4: The competency conformity level of group 3

	Var.	Mean of Perceptions	Mean of Expectations	Conformity Level	Gap (E – P)
	V10	3.05	4.14	73.67 %	1.09
	V11	3.19	4.05	78.77 %	0.86
100	V12	3.35	4.11	81.51 %	0.76

The conformity level of controlling the operation of the ship and care for persons on board competencies is presented in Table 5.

Table 5: The competency conformity level of group 4

Var.	Mean of Perceptions	Mean of Expectations	Conformity Level	Gap (E – P)
V13	3.19	4.17	76.50 %	0.98
V14	3.13	4.15	75.42 %	1.02
V15	3.26	4.32	75.46 %	1.06
V16	3.17	4.15	76.39 %	0.98
V17	3.20	4.10	78.05 %	0.90
V18	3.38	4.21	80.29 %	0.83
V19	3.23	4.17	77.46 %	0.94
V20	3.24	4.09	79.22 %	0.85

Table 5 shows that the level of conformity of controlling the operation of the ship and care for persons on board competency for each variable did not meet 100%. The conformity level of soft skill competencies, group 5, is presented in table 6. Table 6 shows that the suitability level of soft skill competencies for each variable did not meet 100%. Thus, the V21, V22, V23, V24, V25, V26, V27, V28, V29, V30 and V31 variables in the soft skill competencies do not meet what the users expected.

m 11 (m)				_
Table 6. The	competency	conformity	level of group	n 5

Var.	Mean of Perceptions	Mean of Expectations	Conformity Level	Gap (E – P)
V21	3.34	4.01	83.29	0.67
V22	3.06	4.03	75.93	0.97
V23	3.26	4.01	81.30	0.75
V24	3.37	4.01	84.04	0.64
V25	3.26	4.09	79.71	0.83
V26	3.26	4.13	78.93	0.87
V27	3.32	4.05	81.98	0.73
V28	3.3	3.98	82.91	0.68
V29	3.25	4.10	79.27	0.85
V30	3.37	4.16	81.01	0.79
V31	3.34	4.01	83.29	0.67

IPA analysis in this study was conducted on all respondents. Data processing with SPSS 20 obtained images of Cartesian *IPA* diagram on safety aspect in ship for all respondents as follows:




Figure 1: Gap analysis for marine engineering competency

Based on Figure 1, the competency dimensions of marine engineering for V3 and V7 fall within quadrant I (under action). They are considered important by the respondents however they are not as expected. Their perception values are lower than their expectation.

Then, the competency dimensions of the marine engine officer for V1, V2, V5, and V6 fall into Quadrant II (maintain). The perception and expectation level are equally high. This indicates that V1, V2, V5, and V6 are important to the marine engine officers who have high performance related to the variables. This condition must be maintained for the future as it is considered very important/expected as well as the result is very satisfactory.

Next, the competency dimensions of marine engine officers for V4 fall in quadrant IV (over act). The position of V4 according to the respondent has a low level of expectation but it has a good performance. Therefore, it is considered excessive by the respondent. This indicates that V4 which influences the user satisfaction of marine engine officer competencies is considered too excessive in its implementation.




Figure 2: Gap analysis for Electrical, electronic and control engineering competency

Based on Figure 2, the competencyy dimensions of marine engine officer for V8 fall in quadrant I (under action). That is, V8 is considered important by the respondents but what they feel is not what they expected. The perception level of V8 is lower than what the respondent expectation. The same procedure is applied for the competency group 3, 4 and 5.

According Figure 3, the competency dimensions of maintenance and repair for V10 fall within quadrant I (under action). They are considered important by the respondents hovewer they are not as expected. Their perception value are lower than their expectation. Next, the competency dimensions of V11 fall in quadrant III (low priority). This means that V11 is considered less important by the respondent and in fact its performance is not too special. V11 which is contained in quadrant III has low expectation and its performance is also considered unfavourable by the respondent. Increased mastery over V11 needs to be reconsidered. The last competency dimensions of V12 fall in quadrant IV (over act). The position of V12 according to the respondent has a low expectation level but has a good performance, so it is considered excessive by the respondent. This indicates that V12 is considered too excessive in its implementation.




Figure 3: Gap analysis for maintenance and repair competency

Based on Figure 4, the competency dimensions of controlling the operation of the ship and care for persons on board competency for V13, V14, V16 and V19 fall into quadrant I (under action). They are considered important by respondents but they do not feel as they expect. Next, the competency dimensions of V15 and V18 fall into Quadrant II (Maintain).




Figure 4: Gap analysis for controlling the operation of the ship and care for persons on board competency

Respondents assessed the perception and expectation level of the marine engine officer for these variables is equally high. This condition must be maintained for the next time as it is considered expected and the result is very satisfactory. Next, V17 and V20 fall in quadrant III (low priority). V17 and V20 contained in quadrant III have low expectation level and its performance is also considered unfavorable by the respondent. Increased mastery needs to be reconsidered.




Figure 5: Gap analysis for Soft skill competency

Based on Figure 5, the competency dimensions of soft skill for V26 and V30 fall in Quadrant II (Maintain). Respondents assessed the perception and expectation level of the marine engine officer is equally high. This condition must be maintained for the next time as it is considered expected and the result is very satisfactory.

Then, the competency dimensions of V22 fall in quadrant III (low priority). Increasing mastery of V22 needs to be reconsidered. The last is the competency dimensions of V21, V23, V24, V25, V27, V28, and V29 fall in quadrant IV (over act). According to those, the respondent have low expectation but they have good performance.

4 CONCLUSIONS

Several things can be concluded in this research. The first relates to gap analysis showing that almost all research variables suggest a gap although relatively small in value. To see the variables that need to be improved, maintained, not priority for improvement or variables that are above expectation then used the IPA model.

First, it can be summarized that there are several variables that need to be improved such as understand the characteristics the main engine of diesel, steam turbine and gas, including the speed, output and fuel-oil consumption (V3), maneuver the ship (V7), operate electrical, electronic and control systems (V8), manage safe and effective maintenance and repair procedures (V10), ensure compliance with pollution prevention requirements (V13), maintain the seaworthiness of the ship (V14), operate life-saving appliances (V16), and application of leadership and team working skills (V19). These

variable variables need to get attention for future improvements.

There are several variables that need to be maintained such as: shipboard engine operation (V1), maintain a safe Engine Room watch (V2), respond to emergencies (V5), manage fuel oil, lubrication and ballast operation (V6), prevent, control and fight fires on board (V15), monitor compliance with legislative requirements (V18), integrity (V26), and wise attitude (V30).

Next, there are variables that also need to become attention by the respondents to increase the self-mastery such as: detect and identify the causes of engine damage and repair (V11), apply medical first aid on board ship (V17), contribute to safety of personnel and ship (V20), organize and coordinate staff to achieve company objectives (V22), and leadership pattern (V29).

Last, variables that are considered excessive in implementation should also get attention. The variables are practical knowledge on operation, supervision, performance assessment and security maintenance of the installation of the main engine and auxiliary machineries (V4), maintenance and repair of electrical and electronic equipment (V9), ensure safe working practices (V12), team work (V21), continuously learning and willingness to receive feedback from super ordinate (V23), finding problem (V24), using and acting upon information (V25), motivation (V27), persistence and courage in facing problem (V28), and responsibility (V31).

The results of this study provide feedback to the marine engine officers to further enhance the competence during individual ship work. To support this, a marine engine officers may propose the application for training on board or training at a training institution while on vacation. In addition to these training institutions could also use the results of this study to increase the competence areas considered by the marine engine officers which are less satisfied. The shipping company may also undertake enhanced training for shipboard engineers on board with ongoing training programs

ACKNOWLEDGEMENTS

The authors would like to thank to Sekolah Tinggi Ilmu Pelayaran Jakarta9 for providing the opportunity to conduct this research.

REFERENCES

- Ahmed, E., & Braithwaite, V. 2004. *Bullying and victimization: cause for concern for both families and schools.* Social Psychology of Education, 7, 35-54.
- Franklin, Maren. 2005. Performance Gap Analysis: Tips, Tools and Intelligence for Trainers. USA: ASTD Press
- IMO. 2010. Standard of Training Certification Wathkeeping for Seaferers (STCW) Amandemen Manila 2010. London: PEFC
- John A. Martilla and John C. James. 1977. *Importance-Performance Analysis*. Journal of Marketing. January. pp. 977 79.
- Moeheriono. 2012. Pengukuran Kinerja Berbasis Kompetensi (Competency Based Performance Measurement). Jakarta: Raja Grafindo Persada.
- Snyder, C. R. 1994. *The Psychology Of Hope: You Can Get There From Here*. New York: Free Press.
- Syamsudin M. 2007. Urgensi Perlindungan Hukum Pelaut Indonesia Menghadapi Berbagai Permasalahan Global (The Urgency of Legal Protection of Indonesian Seafarers Facing Global Problems). Semarang: Jurnal Hukum Khaira Ummah. Vol. II, No.
- Waidi. 2006. The Art of Re-engineering Your Mind for Success. Jakarta: Gramedia.

